Trease on energoney trake drunt I Sheila of Steel / gin Thick oring Tire exchange partly Empty
Trone reflections for forward Hole in exhaust pipe om rear end 2 little clearance Thelivein pipe + rearette , an portion geshaust line toose Eraust leak at shaft I manufold Hobeh is placed in returnment mulsheild hor marked as shallingered, olso me glass intrance door Heft rear glass V Dork steering arms loose. test very lang V Sasoline leak at tank take off. Seats + up hostery impour shape. Headlight bulb burned out Orighe sertificate Copy of trade name Cultivate Teer, Senios name on side of bus.

Par capacity on registration